



VDOT

Infrared Bridge Deck Scanning


SUMMARY

	Insignificant	Moderate	Severe
Crack Size	< 1/16"	1/16" to 1/4"	>1/4"

In 2012, NEXCO West-USA worked with the Virginia Department of Transportation (VDOT) on a pilot project for the usage of mobile bridge deck scanning. The purpose of the project was primarily to identify cracks and delamination on the target bridge carrying I-64 over Shockoe Valley.

The technology proved effective in the identification and quantification of both cracks visual on the deck's surface, and sub-surface delamination detectable only by infrared.

Bridge owners can use this information to prioritize the bridge deck repair and/or adjust rehabilitation schedules to allocate limited budgets and obtain the maximum return on investment for network level bridge management.



OVERVIEW

Client:	VDOT
Contact info:	Mr. Claude S. Napier, Jr (804-786-2853)
Quantity:	35,000 sqft
Project period:	Nov. 2012



NEXCO - West USA
8300 Boone Blvd. Suite 260
Vienna, VA 22182

+1 (703) 734 - 0281
info@w-nexco-usa.com
www.w-nexco-usa.com