




Two Subway Stations in NY and NJ Water Leak Inspection

OVERVIEW

In 2020, NEXCO-West USA worked on a rehabilitation project with a subway agency in the New York City area. The project scope included the inspection and rehabilitation of two complete station interiors.

The scope of work included the detection of water infiltration, efflorescence, and other overt deficiencies in the stations' structural walls. Infrared and visual scanning data was captured by entering each station room and recording rows of imagery.

Based on the imagery collected by our system, we were able to analyze and report on the locations of water infiltration and heavy efflorescence. Plan and elevation-view maps were provided for efficient review on our online viewing platform.



OVERVIEW

Clients:

[Prime consultants' info withheld]

Contact info:

[Contact info withheld]

Project period:

August, 2020 - September, 2020



NEXCO - West USA
8300 Boone Blvd. Suite 260
Vienna, VA 22182

+1 (703) 734 - 0281
info@w-nexco-usa.com
www.w-nexco-usa.com